Document Log Item

Addressing			
From		То	
Christine Katin/R9/USEPA/US		james.b.sullivan2@navy.mil james.b.sullivan2@navy.mil	
сс		ВСС	
"Campbell Merrifield"			
<campbell.merrifield@tetratech.com></campbell.merrifield@tetratech.com>			
"David Clark" <david.j.clark2@navy.mil></david.j.clark2@navy.mil>			
"Gary Foote" <gary.foote@amec.com></gary.foote@amec.com>			
<james.b.sullivan2@navy.mil></james.b.sullivan2@navy.mil>			
"Remedios Sunga" <rsunga@dtsc.ca.gov></rsunga@dtsc.ca.gov>			
"Scott Anderson" <scott.d.anderson@navy.mil></scott.d.anderson@navy.mil>			
Ross Steenson <rsteenson@waterboards.ca.gov></rsteenson@waterboards.ca.gov>			
Description			Form Used: Reply
Subject		Date/Time	
Treasure Island - Mar. 3, 2010 Draft LUC RD for Site 30		04/05/2010 05:44 PM	
# of Attachments	Total Bytes	NPM	Contributor
0	7,113		
Processing			
Comments			

Body

Document Body

Mr. Sullivan - I reviewed the Draft LUC RD/RA Work Plan for Site 30 and Ross Steenson's comments, which were provided via email on March 26.

The ROD for Site 30 specifies that "ICs would require inspection, maintenance, and reporting of the Site 30 Concrete Pad and Building 502 building slab to ensure remedy compliance" (page 26). The section on LUCs specifies that inspection of the Building 502 slab is required, but does

not mention inspection of the Concrete Slab. If this section is revised, please consider revising the description of ICs to specify the components that apply to the Concrete Pad and the Building 502 slab.

I have no additional comments on the document. Please call/email with any questions. Thank you for the opportunity to review the document.

Christine Katin U.S. EPA, Region 9 San Francisco, CA (415) 972-3112

"Ross Steenson" ---03/26/2010 02:51:49 PM---Mr. Sullivan, Attached are my comments on the subject document. Please contact me if you have any q

From: "Ross Steenson" < RSteenson@waterboards.ca.gov>

To: "Gary Foote" <Gary.Foote@amec.com>, "Remedios Sunga" <rsunga@dtsc.ca.gov>,

Christine Katin/R9/USEPA/US@EPA, "Jeff Austin" < Jeff.Austin@lennar.com>, "William Carson" < william.carson@lfr.com>, "David Clark" < david.j.clark2@navy.mil>, "Jim Sullivan" < james.b.sullivan2@navy.mil>, "Scott Anderson" < scott.d.anderson@navy.mil>, "Jack Sylvan" < jack.sylvan@sfgov.org>, "Mirian Saez" < mirian.saez@sfgov.org>, "Campbell Merrifield"

<Campbell.Merrifield@tetratech.com>

Date: 03/26/2010 02:51 PM

Subject: Treasure Island - RWQCB Comments on Mar. 3, 2010 Draft LUC RD for Site 30

Mr. Sullivan,

Attached are my comments on the subject document. Please contact me if you have any questions.

Regards,

Ross A. Steenson, PG, CHG Engineering Geologist San Francisco Bay Regional Water Quality Control Board Groundwater Protection Division 1515 Clay Street, Suite 1400 Oakland, CA 94612

Phone: (510) 622-2445 Fax: (510) 622-2460

Email: rsteenson@waterboards.ca.gov

[attachment "20100326_Treasure Island_RWQCB Comments on Mar 3, 2010 Draft Site 30 Land Use Controls Remedial Design.pdf" deleted by Christine Katin/R9/USEPA/US]